7178-479-3

# <u>Digital Rate Meter</u>

*TI-1000* 

# Operation Manual

CE



Ver. 3(2019. 07.01)

Please read this Operation Manual including the following precautions carefully to ensure safe use of your meter.

$\underline{/!}$ <caution></caution>	Do not use this product for applications outside of the product specifications.						
$\underline{/!}$ <caution></caution>	Please keep the load not greater than rating.						
<u>/!</u> <caution></caution>	Direct sunshine is avoided, and ratings are used in the place of each Onshime and the place where the be dewy occurs easily. Do not do.						
<pre>/!</pre>	Do not use it in the place with the combustible gas and the ignition thing.						
<u>/!</u> <caution></caution>	o not use it where the temperature and relative humidity exceeds rating, nd where the dew condensation occurs easily either.						
<caution></caution>	Do not subject the unit to strong vibrations or shocks.						
$\underline{/!}$ <caution></caution>	Do not allow metallic debris, dust, or moisture to penetrate the unit.						
$\underline{/!}$ <caution></caution>	Please separate wiring of input signal line and main part of the product from source origin of noise and the static—ridden strong electric wire.						
<u>/</u> <caution></caution>	For safety, professional wiring electrical work, such as electrical wiring is please go. Please shut off the power when electrical wiring.						
$\underline{/!}$ <caution></caution>	Do not touch the terminal while operating. It gets an electric shock.						
<u>/!</u> <caution></caution>	Do not neither take apart the product nor touch its inside when powered on . It could lead to risk of electric shock.						
$\underline{/!}$ <caution></caution>	Wipe it with a dry cloth when you clean the meter.						
/! <caution></caution>	Devices to be connected to each terminal of the terminal block, use the one that is properly isolated from hazardous live parts.						
<u>/</u> <caution></caution>	Since there is no power switch in this machine, it will be in an operating state immediately after power supply impression. Equipment to be incorporated in the side of our customers, please be prepared to supply the switch and circuit breaker which adapted to IEC/EN60947-1 or IEC/EN60947-3 standard in the position that you can operate immediately in emergency. Moreover, please specify that they are interrupting devices.						
<u>/!</u> <caution></caution>	This machine is designed to be used with the panel mounted. When used in a state other than that, there is a possibility that the protective device is provided with is impaired.						
<u>/!</u> <caution></caution>	Use the temperature rating 70 $^\circ\!\mathrm{C}$ or more power cord.						

This product is a panel mount meter that can measure Speed/Rotation/Flow rate/Ratio /Shot speed/Street time/Cycle timer/Stopwatch.

The preset output function of two points has been equipped normally. The preset output two points and the analogue signal outputs can be added in the option.

Contents
1. About confirmation of an attachment, and a guaranteed period ••••• 1
2. Specifications $\cdots \cdots \cdots$
3. Mounting meter ••••••••••••••••••••••••
4. Names and functions of components on front $\cdots \cdots \cdots$
5. Connecting terminal boards $\cdots \cdots = 8-9$
6. Construction of input circuit ••••••••••••••••••••••••••••
7. Setting the dip switch $\cdots \cdots \cdots$
8. The setting menu $\cdots \cdots \cdots$
9. Initialization and program setting $\cdots \cdots 14-17$
10. Content and setting the each mode $\cdots \cdots 18-35$
Content of the each mode and set value • • • • • • • • • • • • • • • • • • •
1 1. Mode protect function ••••••••••••••••••••••••••••••••••••
12. Teaching function •••••••••••••••••••••••••••••••••
13. Calling up and modifying the preset value setting ••••••••••••••• 38
14. Adjusting the analog output (Option:A) ••••••••••••••••••••••••••••••••••••
15. External dimensions $\cdot \cdot \cdot$
16. About a noise countermeasure
17. Troubleshooting •••••••••••••••••••••••••••••••••

### About confirmation of an attachment.

When you received as a product, please confirm whether it includes the following.

(1) TI-1000 (The chosen specif	ication) •••••••••••••	1
(2) TI-1000 Operation manual	(This book) • • • • • • • • • • • • • • • •	1
(3) Unit label (Attachment)	••••••	1

If there are the mistaking parts and the missing parts, please inform a dealer or us. (There is a case that you don't attach by convenience.)

#### About a guaranteed period and a guaranteed area.

#### •Warranty period

One year after the dispatch date from Aichi tokei denki facility.

•Warranty scope

We are making every effort to produce our products with high quality, however if a defect which is subject to our liability should occur during the warranty period under normal use, we shall repair the product or replace it with a normal product for free.

Please understand that we shall determine whether the free remedy shall apply to your situation after our investigation of the product.

Also please understand that the free remedy shall not be applied to a defect:

- 1) Caused by use which does not follow the instructions given in our catalog, product specifications, and/or handling manual,
- 2) Caused by disaster such as a fire, earthquake, storm, flood, or lightening, or a destructive act such as a crime,
- 3) Caused by corrosion due to use in a corrosive environment,
- 4) Caused by acts of animals such as a dog, cat, rat, or insect,
- 5) Caused by a factor other than our product,
- 6) Which could not be foreseen with the science and technology levels at the time of shipment,
- 7) Caused by a repair or alteration other than done by or specified by us, and/or
- 8) Caused by an inappropriate inspection and/or maintenance or replacement of a consumable.

Please note that "warranty" in this context means warranty for our product alone and we shall not reliable for any damage resulting from a defect of our product, including but not limited to a damage to equipment other than our product, loss of profit, loss of opportunity, transportation fee, and construction fee.

# 2. Specifications

# (1) Standard specifications

Item		Specifications					
	Measuring types	Ratemeter (speed, rotation,flow rate,), differential rate, ratio, shot speed, passing time, cycletimer, stop watch					
	Measuring system	Periodic sampling operation					
	Scaling (Pulse rate)	1×10 <sup>-9</sup> – 9999 (selectable)					
		< speed, rotation, flow rate, differential rate, ratio, passing time > ±0.05% F.S. ±1 digit ( at Sampling time for 0.5 second or more , per one input )					
	Measurement accuracy	< shot speed > ±0.1% rdg. ±1digit ( in one measurement less than 100Hz )					
Rate		< cycletimer, stop watch > ±2mS ±1digit ( in one measurement )					
meter	Display	7 segment red color LED (character height : 14mm) ×5 digits					
	Indication area	-9999~99999 (When indication overflowed, 99999 or -9999 blinking)					
	Decimal point	Displays 1 - 3 decimal points. (selectable)					
	Time unit	Per hour , per minute , per second (selectable)					
	Sampling time	Rate reading averaged by 0.1-99.9sec (selectable)					
	Display mode	Blank, Real, least significant digit fixed at 0, or 0/5 (selectable)					
	Moving average	Averaged by 1 – 19 input pulses. (selectable)					
	Auto zero time	The time (0.5-120 sec. selectable), following input stop, at which the reading returns to zero.					
	Measurement reset	Front reset key and Reset input of terminal stand					
	Sensor input signal	NPN open collector pulse input (10mA min.) or ground contact					
	Option input (F)	Voltage pulse input (LOW : 2.0V or lower, HI : 3.8V-30V)					
Sensor	Sensor input	0.01Hz-10kHz (duty 50%)					
input	response	(Low : 0.01–50Hz, Mid : 0.01Hz-1kHz, Hi : 0.01Hz-10kHz switch shifting)					
	Sensor power	DC 12V (±10%) 100mA MAX					
	Sensor power (24V)	DC 24V (±10%) 60mA MAX					
Auviliary	Reset input	50ms or more is turned on, and, reset (terminal board : open collector input)					
input	Hold selection input (Reverse-rotation)	Hold / peak hold / bottom hold / Reverse-rotation signal (Mode No.7) (terminal board : open collector input)					

	Mode protect	Protection of the mode setting		
	Data backup	Each mode setting value is memorized by FRAM (The memory number of times is within 100,000 times, About 10 year safekeeping.)		
	Power supply	AC 100-240V (-15% / +10%) 120mA max 50/60Hz approx 20VA		
	Power supply (DC)	DC 12-24V ±10%		
		DC type is outside the scope of CE Marking.		
Others	Operating temperature / humidity conditions	0-50°C / 30-80% RH (non-condensing)		
	Weight / Dimensions	approx 400g / W96 $ imes$ H48 $ imes$ D130 (mm)		
	Case-material	ABS color (Terminal board PBT Black color)		
	Case-Color	Black		
	Protection class	IP66 「Front only」		
	Installation	The indoor use. Altitude 2,000m max		
	environment	Overvoltage category ${\ensuremath{\mathbb I}}$ , Pollution degree 2		

### (2) Output specifications

«NPN Open collector Preset output : standard equipment»

Output terminal	Output terminals No.9-6(OUT1),10-6(OUT2) (COM common)					
Output condition	Judgment output is compared with the indication value by pre-set value.					
Output system	NPN Open collector output 2 stages (DC 30V 50mA max)					
Output indication	During preset output, the OUT1 and OUT2 LEDs are activated.					
	Front reset key and Reset input of terminal stand					
Oulpul resel	(50ms or more is turned on)					
Time to prohibit judgment	The preset output function is disabled for the specified time					

《Photo MOS relay Preset output: K option》

Output terminal	Output terminals No.15-16(OUT3),17-18(OUT4)
Output condition	Judgment output is compared with the indication value by pre-set value.
Output system	Photo MOS relay output 2 stages ("a" point of contact)
	(Voltage : AC140V DC30V , Load current : 0.12A max)
Output indication	During preset output, the OUT3 and OUT4 LEDs are activated.
	Front reset key and Reset input of terminal stand
Oulput reset	(50ms or more is turned on)
Time to prohibit judgment	The preset output function is disabled for the specified time

«Analog output : A option»

Output terminal	Output terminals No.19-20 (Analog output)
Current output (AI)	DC 4 - 20mA load impedance 500 $\Omega$ or less
Output accuracy	Within $\pm 0.3\%$ F.S. for indicated value (at 23°C)
The temperature characteristic	±100 ppm∕°C
Output response	Approx 50ms (But, an output change is time until the 90% arrival.)
Output resolution	<ul> <li>12-bit D/A conversion operation DC4-20mA : 4000 resolution</li> <li>*Maximum output area : It's possible to output to 102.3% to the maximum of each output.</li> <li>*An analog output is outputting calculation to the indication value shown to 7segment LED. Therefore the resolution sometimes falls from 4000 by setting of Mode No. "C" and "d".</li> </ul>

### How to mount meter



Please push the Fitting for fixing the body. Into a right and left both sides of the meter.

2.



З.

Fig.2



Slide in the rear side (terminal stand side) as for the fitting for fixing the body. It turns a screw by the driver. The meter is fixed (right and left both sides)

Fig.3

/1\

# <Caution>

- 1. Please install it horizontally.
- 2. Fit the body on to a panel 1.0-4.0 mm in thickness.
- 3. Please do not tighten the screw of the mounting bracket too much.
  - (The case might be damaged when tightening too much.)
- 4. When you mount the machine, please provide a space of at least 20mm from the wall in the direction of up and down, right and left and rear(terminal stand side).



### (Display unit ( A to E )

Measurement state : Measurements are displayed.

Setting state : When the mode is set, it displays it as follows.

A • • • • Mode No. is displayed.

B - E • • • Mode items such as the converted value, etc are displayed.

: When the preset output is set, the value input now is displayed.

: When the teaching function is set, the value set now is displayed.

### 2-5Preset output lamp

Measurement state : When the preset output is output, it lights.

Setting state : When the preset output is set, OUT1-4 that is setting it now is displayed.

### 6, 7 Each input display lamp

Measurement state : When Mode No.0 BC is "02"-"07" (ratio measurement), the measurement display switch of Ratio measurement (A and B input lamp is turned off)/ A input measurement (A input lamp light.)/ B input measurement (B input lamplight.) can be done.

Setting state : The set A input measurement or B input measurement lamp lights when the teaching function is set.

#### 8Hold display lamp

Hold input function is set in Mode No.7 B. (Refer to P.30) When the hold input of the terminal stand is turned on, and the holding operation is done, it lights.

### 9 Mode key 🕡

Measurement state : It enters the mode setting state if 1 + 1 > 1 are pushed for 2 sec. or more.

: It enters the preset output setting state if only is pushed for 2 sec.or more.

Setting state : When the mode is set, the mode number is raised.

When the preset output is set, OUT1-4 is changed.

# 10 Up key 🛆

Setting state : When each setting it, the numerical value of a set digit is raised.

## 1) Down key 💎

Measurement state : When this key is pushed for 2 sec. or more, the state of the mode protecting is displayed. (Refer to P.36 Mode protect function)

Setting state : When each setting it, the numerical value of a set digit is lowered.

# 12 Shift key

Measurement state : When Mode No.0 BC is "00" (A input measurement) or "01" (B input measurement), The teaching function works. (Refer to P.37 Teaching function)

Setting state : When each setting it, a set digit is shifted to a right digit.

# 13 Enter key

Measurement state : When Mode No.0 BC is "02"-"07" (ratio measurement), the measurement display switch of Ratio measurement / A input measurement / B input measurement can be done.

Setting state : When the mode is set, and the preset output is set, a set value is registered, and it returns it to Measurement state.

### 14 Reset key (RST)

Measurement state : When this key is pushed for 2 seconds or more, the output of measurement reset (Indicated value 0) and preset output OFF.

Setting state : When the mode is set, and the preset output is set, a set value is not registered, and it returns it to Measurement state.



Fig.5

# $\underline{/!}$ <Caution>

- 1) For safety, professional wiring electrical work, such as electrical wiring is please go. Please shut off the power when electrical wiring.
- 2) Power supply confirmation
- Confirm the specification of the AC power supply type and the DC power supply type well.
- DC power supply type notes the polarity.5
- 3) Wire correctly after often confirming the terminal stand label.
- 4) The wiring technique is different depending on the kind of the sensor.Wire correctly referring to the connection diagram (P.9) and the manual of the sensor.The sensor and the meter might break down when connecting it by mistake.
- 5) Do not use the sensor power supply for the usages other than the sensor.
- 6) Tighten the screw of the terminal stand surely.
- 7) Do not touch the terminals while power is being supplied. There is a risk of electrical shock.

A. Pulse output 2-wire type sensor Fig.6



B. Ground contact output sensor





C. Pulse output 3-wire type sensor



### NOTE

- When mis-counting by the chattering of the having point of contact input, (Relay etc.) Connect the electrolytic capacitor with terminal stand
   6–7 (A input) and 6–8 (B input) according to the frequency.
- When mis-counting because of the noise etc, Connect the film capacitor with the same terminal according to the width of the input frequency and the noise.

### ① NPN open collector pulse input



2 Voltage pulse input







Sensor input, and relationship of the sensor input response is shown in Table1.

						Та	ble.1
	B.IN		A.IN		B.IN	A.IN	
	1	2	З	4	5	6	
Input frequency 0.01Hz - 50Hz LOW	ON	OFF	OFF	ON			
Input frequency 0.01Hz - 1kHz MID	OFF	ON	ON	OFF			
Input frequency 0.01Hz - 10kHz HI	OFF	OFF	OFF	OFF			
NPN open collector input					ON	ON	
Voltage pulse input					OFF	OFF	
		1	2 3	4 5	● 0I 〔 ① 6	N F	

When a sensor optional input is not specified, sensor input is "NPN open collector", and Sensor input response is "HI".





### ≪Test Mode≫





Registered by

Please recommend to take notes of the value setting of each mode.

Returns without registering.

User can change the set value. Table 3 illustrates variation of default value.

Initialization is to be performed when powered on, pressing ENT key (m).

In case of which computer requires runaway reaction e.g. when disturbed by noise or so, please initialize it and reset the value that you wish to have.

		Table 2
Operating Key	Indication	Procedure
BNT	A B C D E P r o − Program No. ←	Turn on the power while pressing the ា key. The program is displayed No.0.
	A B C D E P r o − ↑ 0~A	changes the flash figure. Each time the key is pressed, a flash figure is rising up.
	A B C D E P r o − ↑ 0~A	<ul> <li>▽ changes the flash figure.</li> <li>Each time the key is pressed, a flash figure is down.</li> </ul>
INT		After adjusting the setting, use (m) to register it. It returns to the measurement display after a set value is registered.

### <Program setting>

Program		Pro-1	Pro-2	Pro-3	Pro-4	Pro-5	Pro-6	Pro-7	Pro-8	Pro-9
	Pro-0					0F05	OF10	VN05	VN10	VN20
Mode No.		NDOO			TNDZO	0100		*	*	*
0.	0021	0012	0011	0011	0011	0013	0012	0013	0012	0012
1.	1000	2500	7692	7692	2500	4600	2500	8333	8333	5000
2.	3002	6002	6002	6002	5002	7002	6002	8002	7002	6002
З.	1000	2500	7692	7692	2500	4600	2500	8333	8333	5000
4.	3002	6002	6002	6002	5002	7002	6002	8002	7002	6002
5.	1000	1000	1000	1000	1000	1000	1000	1000	1000	1000
6.	02.0	02.0	02.0	02.0	02.0	02.0	02.0	02.0	02.0	02.0
7.	0_00	0_00	0_00	0_00	0_00	0_00	0_00	0_00	0_00	0_00
8.	0000	0000	0000	0000	0000	0000	0000	0000	00000	0000
9.	0000	0000	0000	0000	0000	0000	0000	0000	0000	00000
A.	0000	0000	00000	0000	00000	0000	0000	0000	00000	0000
b.	0000	0000	0000	0000	0000	0000	0000	0000	00000	0000
C.	_10_	_10_	_10_	_10_	_10_	_10_	_10_	_10_	_10_	_10_
d.	1000	0300	0200	0100	0600	0850	0500	1000	1000	6000
E.	0	0	0	0	0	0	0	0	0	0
F.	0_01	0_01	0_01	0_01	0_01	0_01	0_01	0_01	0_01	0_01
OUT 1	00250	00075	00050	00025	00150	00213	00125	00250	00250	01500
OUT2	00750	00225	00150	00075	00450	00638	00375	00750	00750	04500
OUT3	00250	00075	00050	00025	00150	00213	00125	00250	00250	01500
OUT4	00750	00225	00150	00075	00450	00638	00375	00750	00750	04500
Location of decimal point	0,0000	000.000	00000.0	0000.0	0000.0	00,000	000.00	00.000	000.00	000.00

Default value of mode for each program



\*When output of VN is set at "frequency pulse 200Hz"

## <Mode setting when VN (output setting : unit pulse) is connected $\geq$

Please comply fully with the settings illustrated at Table 4 when connecting sensor is VN (Output setting : unit pulse).

Sensor Mode No.	VN05	VN10	VN20
0.	0013	0012	0012
1.	1000	1000	1000
2.	6002	5002	4002
З.	1000	1000	1000
4.	6002	5002	4002
5.	1000	1000	1000
6.	02,0	02.0	02.0
7.	0_00	0_00	0_00
8.	0000	0000	0000
9.	0000	0000	0000
A.	0000	0000	0000
b.	00000	0000	0000
С.	_10_	_10_	_10_
d.	1000	1000	6000
E.	0	0	0
F.	0_01	0_01	0_01
OUT1	00250	00250	01500
OUT2	00750	00750	04500
OUT3	00250	00250	01500
OUT4	00750	00750	04500
Location of decimal point	00.000	000.00	000.00

Setting of VN (output : unit pulse) Table 4

# <u>/!</u><Caution>

\*When initialization is performed existing setting values turn back to the default, so please make sure you preserve the records of all the setting values before initialization.

### Setting value of each mode

Setting value of alarm presetting

			Notes		
	А	В	С	D	E
OUT1					
OUT2					
OUT3					
OUT4					

Mode No.	Notes			
А	В	С	D	E
0.				
1.				
2.				
З.				
4.				
5.				
6.				
7.				
8.				
9.				
Α.				
b.				
С.	_			—
d.				
E.	_	_	_	
F.		_		

### $\ll$ 1. Operating method (the mode setting) $\gg$

When doing mode setting, please operate as follows. Table.5		
Operating key	Indication	Procedure
	A B C D E O. O 2 1 ↓ ↓ ↓ Mode No. Data value	While pushing down were, press for 2 sec. or more. "O" appears in displays A ,the value setting for Mode No.O is shown.
	A B C D E 0. <b>0</b> 0 2 1 ↑ 0-9	
	A B C D E 0. 9 0 2 1 ↑ 9-0	<pre></pre>
	A B C D E O. $\bigcirc$ O 2 1 $\bigwedge^{\rightarrow} \xrightarrow{\rightarrow} \xrightarrow{\rightarrow}$	A figure of flash indication is shifted. Each time the key is pressed, a flash figure is shifted, to the right.
WODE	A B C D E 1. <b>1</b> 0 0 0 ↑ 0-9, A,b,C,d,E,F	The Mode No. is changed. Each time (more is pressed, the Mode No. is rising. $(0 \rightarrow 1 \rightarrow \cdots \rightarrow F \rightarrow 0 \rightarrow 1 \cdots )$ All modes are "1-F". When the Mode No. reached "F", return to "0".
INE		After adjusting the setting, use () to register it. It returns to the measurement display after a set value is registered.
RST		It returns to the measurement display without registering a set value.

### When doing mode setting please operate as follows

# /! < Caution >

\*Please make the mode protect function "L-off" at the mode setting. If it's a condition of "L-on", it can't be changed.

About the contents of the mode protect function, please refer to "11.Mode protect function".

Mode No.	Measuring types, Measurement unit, Display decimal point
0	A B C D E O. O O 2 1 Display decimal point setting O: O 2: 0.00 1: 0.0 3: 0.000 Measuring unit O: hour 1: minute 2: second 3: hour-minute 4: minute-second 08,13 - 15 alone can be used.
	<ul> <li>Measuring types</li> <li>OO : A-input : speed, rotation, flow rate measurement</li> <li>O1 : B-input : speed, rotation, flow rate measurement</li> <li>O2 : Ratio measurement (absolute ratio measurement) B/A×100</li> <li>O3 : Ratio measurement (error ratio measurement) (B-A)/A×100</li> <li>O4 : Ratio measurement (difference measurement) A-B</li> <li>O5 : Ratio measurement (density) B/(A+B)×100</li> <li>O6 : Ratio measurement (sum measurement) A+B</li> <li>O7 : Ratio measurement (sum measurement) (A+B)/R or (A-B)/R</li> <li>O8 : Passing time measurement</li> <li>O9 : Shot speed UB1 (1 senor one direction speed)</li> <li>10 : Shot speed UB2 (1 sensor reciprocal speed)</li> <li>11 : Shot speed UC (2 sensor reciprocal speed)</li> <li>12 : Shot speed UC (2 sensor reciprocal speed)</li> <li>13 : Cycle-timer measurement</li> <li>14 : Stop watch A</li> <li>15 : Stop watch B</li> <li>NOTE : Upon setting 16 - 19, same operation as with 00 is mode.</li> </ul>
	Option : A In analog output, The real-time output functions only when I set Mode No.0 "00"(A input) or "01"(B input) or "08"(Passing time measurement). Otherwise, set it in 1 (Synchronizes for the display).
	When use analog output, the measurement unit choose O(hour) or 1 (minute) or 2 (second).
(00) (01)	(Ratemeter) When I use it in Ratemeter (speed, rotation,flow rate), choose this mode. Choose "00"(A input) or "01"(B input).









Mode No.	A-input : Setting of scaling data
1	A B C D E 1. 1 0 0 0 Scaling data : 0001 – 9999 (Do not set 0000)
	Please set the pulse rate (scaling data) of the sensor. 4 digit of numerical value to set with this mode, and please input Exp.value of Mode No. 2. Then $1 \times 10^{-9} \sim 9999$ " can set the magnification per 1 signal.
	Measuring types : 08(Passing time measurement), set it in unit "mm/p" Measuring types : 09 $\sim$ 12(shot speed), set the distance between the sensor.
	(Ex.) Using a flow sensor which emits 1 pulse per 1.234mL, the cumulative total flow in liters can be expressed using the following conversion.
	1.234mL $\longrightarrow$ 0.001234L $\longrightarrow$ <u>1234</u> $\times$ 10 <sup>-6</sup> Scaled to the desired unit (L) $\uparrow$ $\uparrow$
	4 digits(Scaling data) Exp. Value(exponent) A B C D E Mode No.1 1. 1 2 3 4 A B C D E Mode No.2 2. 6 * * *
	The above is based on the example of flow rate measurement, while for examples of conversion value, refer to next page.
	For ratio-measurement, sensor is connected to A and B for each 1 piece, then, set Mode No."3"and"4".

# Calculation example of scaling data (setting example)

Example	Arithmetic expression
Arithmetic expression	In case of "Revolution" Scaling data=1 revolution/pulse In case of "Speed" Scaling data=Amount of transfer/pulse In case of "Flow" Scaling data=Flow rate value/pulse
(Ex.1) Revolution	Factor $\rightarrow$ 1 revolution/1 pulse =1 $\sqrt{-}$ Exp. value "Mode No.2" $0001 \times 10^{-0}$ or $1000 \times 10^{-3}$ $\sqrt{-}$ "Mode No.1" $\sqrt{-}$ "Mode No.1" $\sqrt{-}$ "Mode No.1" $\sqrt{-}$ "Mode No.1" $\sqrt{-}$ "Mode No.1" $\sqrt{-}$ The right side". Sensor The right side can be adjusted slightly.
(Ex.2) Revolution	Factor $\rightarrow$ 1 revolution/30 pulse=1/30=0.033333 $3333 \times 10^{-5}$ $\uparrow$ $Mode No.1" \rightarrow Exp. value ~Mode No.2" \Rightarrow $
(Ex.3) Speed	Factor $\rightarrow$ The speed of "Drive roller; 100 $\phi$ " is indicated. Scaling data=Amount of transfer/pulse Scaling data=100× $\pi$ /30=10.47197mm In case of "mm/min" 1047×10 <sup>-2</sup> In case of "cm/min" 1047×10 <sup>-3</sup> In case of "m/min" 1047×10 <sup>-3</sup> In case of "m/min" 1047×10 <sup>-5</sup> In case of "m/min" 1047×10 <sup>-5</sup>
(Ex.4) Flow	Factor → 7.692mL/pulse Scaling data=Flow rate value/pulse In case of "mL/min "7692×10 <sup>-3</sup> Flow → In case of "L/min "7692×10 <sup>-6</sup> sensor ↑ Mode No.1" ↑ Exp. value
(Ex.5) Shot Speed	Factor $\rightarrow$ length between 2 points =24mm (In case of 2sensors, length between sensors) K=Input moving length between 2 points In case of "mm/min" 2400×10-2 In case of "cm/min" 2400×10-3 In case of "m/min" 2400×10-5 A Sensor Mode "1" EXP Value
	As well as when two sensors are used, set the mode <u>1</u> and <u>2</u> only. Ignore mode <u>3</u> and <u>4</u> .

Mode No.	A-input : Exp.value, moving average, auto-zero time
2	A B C D E 2. 3 0 0 2 ↓ ↓ ↓ ↓ Auto-zero time
	0 : Disable 5 : 10 sec. 1 : 0.5 sec. 6 : 20 sec. 2 : 1 sec. 7 : 30 sec. 3 : 2 sec. 8 : 60 sec. 4 : 5 sec. 9 : 120 sec.
	$\longrightarrow \text{Moving average}$
	00-19 times (00 and 01 are equivalent in effect.)
	$  \text{ Exp.value (exponent 10^n)} $ n=0 - 9
	(Exp. Value) The magnification per 1 pulse is decided at registered property of "Mode No.1" and "Exp. value".
	(Moving average range) Set the number of pulses to be averaged. For example, when 04 is set, four pulses are read, calculated, averaged, and indicated. This function is effective in the case that the flow rate value per pulse is not exact. For this calculation, however, the latest one pulse is taken in and the preceding pulse is discharged, and four pulses are read, moving-averaged, and indicated. This function should be applied only at 20 Hz or less.
	 ۲Ev ک
	$\begin{array}{cccccccccccccccccccccccccccccccccccc$
	For example, if fitting angles four blades of the impeller are uneven, the indication is unstable even if the flow rate is constant, but setting 4 for moving average offers average values calculated taking the latest pulses in. And as seen in the above figure, the calculation is made every time when a pulse comes in, but the indicated time becomes that set according to "the setting of the sampling time" of "Mode No.6".
	《Relationship between the moving average range and sampling time》 The newest data, obtained from the moving average performed at the preset sampling interval, is indicated in the reading if sampling is specified.
	(Auto-zero time) If no input signal comes in within the set time, this function returns the reading indication value to "0".

2	(Ex.) The magnification per 1 signal assumes it 0.1234, and the moving average zeroes indication by invalidity five seconds after the last input signal.
2	A B C D E Mode No.1
	<b>1.</b> 1 2 3 4 B~E∶(1234×10 <sup>-4</sup> =0, 1234)
	A B C D E Mode No.2
	2.4004 B: $4$ (Exp value input mentioned above)
	E : 4 (It is indication "O" 5 sec. after the last input signal)







Mode No.	Sampling time
6	$\begin{array}{c ccccccccccccccccccccccccccccccccccc$
	For sampling time, input signal is measured with its set time, and its mean value is calculated and displayed, then, use it for preventing the flashing or for stabilizing the display. Accordingly, renewal shall be made by averaging the display for each set time.
With the setting of 00.0, display is made for each pulse. It is effective with about 1 pulse / seconds , whereas, pay attention to th That the faster pulse induces more flicker.	
	When change sampling time, and after former sampling time was over, it becomes effective

Mode No.	Hold input function setting, display blank, lowest digit display
7	A B C D E 7. 0 0 0 Lowest digit display 0 : Real 1 : Fixed at 0 2 : 0 or 5 Display blank 0 : Normal display 1 : Blank display 1 : Blank display 0 : No use 1 : Peak hold 2 : Bottom hold 3 : Hold 4 : Reverse-rotation input (differential rate measurement)
	<ul> <li>(Hold input function setting)</li> <li>Set a function when ON(short) did terminal stand 2 – 3</li> <li>O: No use Hold input is invalid.</li> <li>1: Peak hold Between ON, it updates a highest value indication level while blinking.</li> <li>2: Bottom hold Between ON, it updates a smallest value indication level while blinking.</li> <li>3: Hold Between ON, It displays a current value while blinking.</li> <li>4: Reverse-rotation input (differential rate measurement) It functions as Reverse-rotation input. (This function becomes invalid other than differential rate measurement)</li> </ul>
	<ul> <li>(Display blank)</li> <li>When I set it to 1, A measured value(7segment LED) and each lamp display it and do not turn on. (But preset put lamp OUT1-4 is excluded)</li> <li>(Lowest digit display)</li> <li>The form of indication for the least significant digit (digit on the right end) is selected.</li> <li>0 : Real • • • • • • • • • • • • • • • • • • •</li></ul>









Mode No.	Analog output : Setting of measurement choice and the output digit (Option A)
С	A B C D E C. 1 0 Digit selection 0: Right 4digits : comparison 1: Left 4digits : comparison 0: Real time output 1: Synchronizes for display 2: Synchronizes for measurement (calculation value)
	(Digit selection) The four digits for comparison output are selected.
	<ul> <li>[Analog output method]</li> <li>O: Real time output The real time is analog output in sync with inside calculation. The real-time output functions only when I set Mode No,O "OO" (A input) or "O1" (B input) or "O8" (Passing time measurement). Otherwise, set it in 1 (Synchronizes for the display).</li> <li>1: Synchronizes for the display The analog output is output for an indication value. When hold input functions, the analog output is output for a displayed value now. (It synchronizes at indication sampling time) For example when a peak hold is functioning, analog output by the present shown value (Peak hold value).</li> <li>2: Synchronizes for the measurement (calculation value) The analog output is output for a calculated value. (It synchronizes at indication sampling time) The difference with 1 (Synchronizes for the display), When it is input hold, not an indication value, it is made analog output for a calculated value.</li> </ul>

Mode No.	Analog output : Setting of maximum output indication (Option A)
d	A B C D E d. 1 0 0 0 Indication value : 0001 - 9999. (Do not set 0000)
	Set an indication value of the time when the analog output is maximum. Set a value in four digits, neglecting the decimal point. For example, both 500.0 and 50.00 are all right. (It sets as "5000" in this case.)
	(Ex.) Setting to output it to the maximum voltage current when it in real time outputs, and the display value becomes 5000 is the following.
	ABCDEMode No."C"C.OOC:O (Real time output)D:O (Right 4digits : comparison)
	ABCDEMode No."d"d. 5000B- E(Setting of maximum output ndication;5000)
	NOTE : he analog output outputs it at absolute value for an indication level. (There are no relations in a plus and the minus of the indication level) In the case of the example mentioned above, it is output as follows.
	20.46mA 20mA 
	<ul> <li>% For an analog output MAX level, it is output linearly to 102.3%.</li> <li>% When setting Mode No. d as (0000), an analog output is always 102.3%.</li> </ul>

When the mode protect function is made effective,  $\triangle$  and  $\bigtriangledown$  operation is invalid by mode setting. Therefore the set value can't be changed.

In an early stage, the mode protect function is invalid .

When doing the mode protect function setting, please operate as follows.

«Operation of the mode protect»

Table.6

Operation key	Indication	Procedure	
	A B C D E L − <u>o F F</u> (The mode protect : present)	Press the key for 2 sec. or more. The present mode protect state is displayed . (The regular factory setting is "L-off".)	
	A B C D E L − <u>o n</u> (The mode protect : change)	Keep pressing $\bigtriangledown$ for 8 sec as it's continuously, the state of mode protect is changed. %" OFF $\rightarrow$ ON" or "ON $\rightarrow$ OFF"	
		It usually returns when $\bigtriangledown$ is stopped being pressed.	

# /!\_<Caution>

\*The preset value setting and the offset value setting always can be changed.\*The mode protection function becomes "OFF", when it's initialized.

### What is the teaching function?

Change the current indication level to any value. (setting automatic as for the scaling data.) [Ex.] when input frequency 100Hz is displayed as 200.0rpm, for changing the

display value from 200.0 to 180.0, converted value may be changed, whereas, upon setting "180.0" by the teaching function, 180.0 is automatically displayed. At this time, converted value is automatically re-written by reverse calculation from the set value as 180.0

Set-converted Scaling data Converted value 3333 EXP 4		Automatically re-written converted Scaling data Converted value 3000 ⇒ EXP 5 Table.7
Operating key	Indication	Procedure
	A B C D E O 2 O O. O	Push D for 2 sec or more. In the case of A input measurement, A input lamp blinks. In the case of B input measurement, B input lamp blinks.
	A B C D E $0 \rightarrow 2 \rightarrow 0 \rightarrow 0 \rightarrow 0$ $\wedge$	A figure of flash indication is shifted. Each time the key is pressed, a flash figure is shifted, to the right.
	A B C D E O 1 8 O.O ↑ O-9	Push this key for changing the value flashing. One figure moves up and down every time it pushes once.
		After input of the desired value from the data value 200.0, push (INT). Upon pushing this (INT) key, the measuring mode returns, and the converted Scaling data and EXP value can be re-written.
RST		It returns to the measurement display without registering a set value.

(The decimal point position links setting of Mode No.0 "E" Display decimal point setting)

# $\underline{/!}$ <Caution >

- This teaching function can set only ratemeter (speed, rotation,flow rate) of A-input and B-input. (Need to set in Mode No.0 'BC' 00 or 01) When it is other measurement types, teaching function becomes invalid.
- Do not make this operation at time of stop or low turning (Frequency).

Set the value to pre-set of the preset out by the following method.

The set range is "-9999" - "99999"

In addition, please refer to Mode No.8-b (P.31-33) for the setting of the preset output.

		Table.8
Operating key	Indication	Procedure
MODE	A B C D E 2 0 0.0 1● 20 30 40	Push () for 2 sec., or more. "OUT1" lamp lights up, and a current preset value is displayed.
	A B C D E 9→ <b>9</b> →9→9→9 ↑ 1● 20 30 40	A figure of flash indication is shifted. Each time the key is pressed, a flash figure is shifted, to the right.
	A B C D E 9 <b>0</b> 9 9 9 ↑ 0-9 1● 20 30 40	Push this key for changing the value flashing. One figure moves up and down every time it pushes once.
	A B C D E 9 9 9 9 9 9 10 2● 30 40	Push ()) key. The OUT1 lamp shifts to OUT2 lamp. OUT2 lamp lights up, and a current preset value is displayed and can set it.
	A B C D E 9 9 9 9 9 9 10 20 3● 40	Push ()) key. The OUT2 lamp shifts to OUT3 lamp. OUT3 lamp lights up, and a current preset value is displayed and can set it.
	A B C D E 9 9 9 9 9 9 10 20 30 4●	Push ()) key. The OUT3 lamp shifts to OUT4 lamp. OUT4 lamp lights up, and a current preset value is displayed and can set it.
		After adjusting the setting, use (INT) to register it. It returns to the measurement display after a set value is registered.
RST		It returns to the measurement display without registering a set value.

(Decimal point of the display value is inter connected with Mode No.O - E.)



- In case selecting the time-measuring time (Mode No.0 08, 13, 14, 15) and the measuring unit (hour-minute) (minute-second), be sure to set the value of display unit C to "O".
- When K option is not equipped with, OUT3 and OUT4 are not output. (only a lamp turns on.)

# /!\_<Caution>

The analog output range is adjusted correctly at a factory. Please do not touch except necessity.

«Adjustment method»

- 1. Power on the (more) being pressed to put the instrument into the test mode.
- 2. Press the more until the analog output test "Ad" appears.
- 3. Please coordinate the ZERO volume with the SPAN volume to become the following output voltage/current. (Please adjust it from the ZERO volume by all means.)

Current output (AI) type unit

Indication	Output current	
0	4 mA	Turn the zero volume to adjust
100	20 mA	Turn the span volume to adjust

(\* Repeat the procedure several times for fine adjustment.)

Fig.13









#### When influence of noise occurred, please be careful about the following.

When doing a blackout and a malfunction by influence of noise, please be initialized. (Refer to P.14) Please take notes of the value setting of each modes. If it becomes normal, please take the following measure. And please setting it once again.

- (1) Do not share the power supply with a power line directly.(When I share a power line, please use an isolation transformers)
- (2) Please use 3 cores of shielding wire for a sensor , separate as much as possible from a source of noise.
- (3) Please avoid a source of noise (power supply line and inverter), make it as short as possible. After that, please install a sensor code.
- (4) A great many noises may be included in F.G. Line of the device. In this case you should not tie F.G. of the meter.



(6) The manner of the sensor cord installation. When there is a power supply line near the sensor cord, a surge and noise are influenced.

Therefore, install a sensor cord independently or for 50 cm or more.

Fig.17 Fig.18 Sensor cord Sensor cord Don't lay the pipes identically. (7) When being affected than other equipment, please use a spark killer like Fig.19 and take a measure. Fig.17 Fig.18 Fig.18 Fig.18 Fig.18 Fig.18 Fig.18 Fig.18 Fig.18 Fig.19 Fig.19 Fig.19 Fig.19

Tact actuator

(8) If there is an unclear point, please even consult with use about a dealer or us.

When abnormality occurred	, please check it as follows.
---------------------------	-------------------------------

No.	Problem	Checking point	Solution
1	Display does not appear at all.	<ul> <li>→Has it connected with the rear terminal correctly?</li> <li>↓</li> <li>→Does a sensor power supply short-circuit?</li> <li>(Or it is an overcurrent)</li> </ul>	<ul> <li>→Connect correctly according to</li></ul>
			When display still does not appear, have it serviced.
2	Unusual • LED lighting, key • switch operation, • preset output, • analog output	→Check with the test mode. (Refer to P.11)	→Initialize(Refer to P.14) When it still does not resume normal status, have it serviced.
3	Remains at "O"	→Is the setting for each mode correct? ↓ →Is the sensor input normal? ↓ ↓ →Is the distance of the sensor normal? ↓ ↓ →Is the input system of this meter suitable for the output signal of the sensor?	<ul> <li>→Check the setting again. (Refer to P.18-35)</li> <li>→Check the connection of the sensor (Refer to P.9). Check with the test mode (Refer to P.12).</li> <li>→The sensor lamp flash is confirmed. A sensor is tested. "ON/OFF"</li> <li>When it still does not resume normal status, have it serviced.</li> </ul>
4	Indicator is flashing "99999" . (Error indication)	→Check whether the scaling is not too large →Influence of noise.	→Change the scaling data. (Refer to P.24-27 for Mode No.1-4) →Noise countermeasure (Refer to P.41)

No.	Problem	Checking point	Solution
5	Indication is not stable	→It is sometimes displayed smaller than a real value. ↓ →It is sometimes displayed more greatly than a real value.	→Detection error of the sensor. check the accuracy of the sensor when there is little quantity of detection →Noise countermeasure
		↓ ↓ →Because the movement of the measurement thing fluctuates, the signal of the sensor sways	<ul> <li>(Refer to P.41)</li> <li>→When it is caused by the chattering such as relays, Please attach a capacitor to the sensor input terminal.</li> <li>→Lengthen sampling time (Refer to P.29)</li> <li>When it still does not resume normal status, have it serviced.</li> </ul>
6	Indication goes out. An indication level becomes than double,	→Influence of the spark noise with a relay or the electromagnetic valve	→Noise countermeasure (Refer to P.41)
7	Other problems		→Have it serviced.

< MEMO >



1-2-70 Chitose, Atsuta-ku, Nagoya, Aichi Prefecture 456-8691 JAPAN Contact us : Overseas Business Division TEL. +81-(0)52-661-5150 FAX. +81-(0)52-661-6418

Aichi Tokei Denki homepage: https://www.aichitokei.co.jp/

The product specification might be changed without prior notice.